


Potentiometer



Reference	To be used with:
1.000	**VKD, TKD, VXE, FE, FK
10.000	**VKD, TKD, VXE, FE, FK
100	**VKD, TKD, VXE, FE, FK
5.000	**VKD, TKD, VXE, FE, FK



Potentiometer

- Upper part (PVC-U)
 - Bottom part (PVC-U)
 - Bolts (zinc plated steel)
 - Nuts (zinc plated steel)
 - Gasket (NBR)
 - Reinforcing ring (Stainless steel)
- The reinforcing bush are used to reinforce the pipe PE100 (SDR11) e PE-X, to along the lifetime of the pipeline and to reduce the collapse risk of the pipe in disadvantages conditions. They use is particularly suggested using PE-X pipes. The two tightening keys (d.16-63 and d.75-110) are important tools to install the **MAGNUM 3G** fittings