


RIV

Reducer: solvent weld spigot (d) or solvent weld socket (d2), solvent weld socket (d1 reduced) or solvent weld spigot (d3 reduced) (Fig.C)



| Reference | | $d \times d[5:2] \times d[5:3] \times d[5:1]$ | PN | E | L | L_1 | $L[5:2]$ | $L[5:3]$ | Z | g |
|-----------------|----|---|----|---|----|-------|----------|----------|----|-----|
| RIV090075050040 | I | 90 x 75 x 50 x 40 | 16 | - | 51 | 26 | 44 | 31 | 74 | 180 |
| RIV090075063050 | IF | 90 x 75 x 63 x 50 | 16 | - | 51 | 31 | 44 | 38 | 74 | 200 |
| RIV090075075063 | F | 90 x 75 x 75 x 63 | 16 | - | 51 | 38 | 44 | 44 | 74 | 260 |
| RIV090075090075 | F | 90 x 75 x 90 x 75 | 16 | - | 51 | 44 | 44 | 51 | 74 | 325 |