


RIV

Reducer: solvent weld spigot (d) or solvent weld socket (d2), solvent weld socket (d1 reduced) or solvent weld spigot (d3 reduced) (Fig.C)



Reference		$d \times d[5:2] \times d[5:3] \times d[5:1]$	PN	E	L	L_1	$L[5:2]$	$L[5:3]$	Z	g
RIV090075050040	I	90 x 75 x 50 x 40	16	-	51	26	44	31	74	180
RIV090075063050	IF	90 x 75 x 63 x 50	16	-	51	31	44	38	74	200
RIV090075075063	F	90 x 75 x 75 x 63	16	-	51	38	44	44	74	260
RIV090075090075	F	90 x 75 x 90 x 75	16	-	51	44	44	51	74	325